


CORNER RECORD

Document Number 02-58
County of San Joaquin, California

City of Lodi

Brief Legal Description Lower Sacramento Road at Paradise Drive



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other

Date of Survey 8/8/99

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found 3/4 inch iron rod in monument box per Maps and Plats 33-71 at the intersection of Lower Sacramento Road and Paradise Drive

A description of the physical condition of the monument as found and as set or reset: The monument is in good condition. Reference point was set in case monument is disturbed.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors Act on November 15, 2002.

Signed Terry Piazza L.S. or R.C.E. Number 19638



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DECEMBER 27, 2002 and examined and filed JANUARY, 2003.

Signed Jeff D. Lund P.L.S. No. 4440

Title Assistant County Surveyor



County Surveyor's Comment This corner record is not in compliance with Board Rule 464(c) regarding submittal within 90 days from the date of survey.

(D.D. Sheet No. 15-A)

SILVER TIP WAY

Lodi West, Unit No. 3
(M.&P. 33-71)

PARADISE DRIVE

SET P.K. NAIL & SHINER
(NO TAG)

EAST LINE OF THE SOUTHWEST 1/4
OF SEC. 3, T.3 N., R.6 E., M.D.B. & M.

95'

LOWER SACRAMENTO ROAD

55'



NOT TO SCALE

LEGEND

SEC.	SECTION
FD.	FOUND
○	FD. 3/4" IRON ROD TAGGED R.C.E. 19638 IN MONUMENT BOX PER M.&P. 33-71
○	SET MONUMENT, AS NOTED BOOK OF MAPS AND PLATS
M.&P.	BOOK OF MAPS AND PLATS

ALL REFERENCES ARE TO SAN JOAQUIN COUNTY
RECORDS AND BOOK OR VOLUME PRECEDES PAGE.

NOTE:

THE TIES SHOWN HEREON ARE FOR THE PURPOSE OF PERPETUATING
THE MONUMENTATION CURRENTLY EXISTING. NO ATTEMPT WAS MADE TO
DETERMINE THE VALIDITY OF THE MONUMENTS OR THEIR PROPER
LOCATION IN RELATION TO LEGAL BOUNDARY LINES IN THE AREA.