


CORNER RECORD

Document Number CR-97-30

City of _____ County of SAN JOAQUIN, California

Brief Legal Description A PORTION OF THE S.E. 1/4 OF SECTION 8, T.1S., R.7E., M.D.B. & M. SHOWN ON R.S. 12-8, S.J.C.R.



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey AUGUST 21, 1997

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

—●— FOUND AS NOTED

A description of the physical condition of the monument as found and as set or reset:

—○— SET 3/4" X 30" IRON PIPE TAGGED L.S. 4450

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on AUGUST 22, 1997.

Signed Michael L. Quarata L.S. or R.C.E. Number L.S. 4450



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received November 26, 1997 and examined and filed DECEMBER 22, 1997.

Signed Henry M. Hirata Title COUNTY SURVEYOR



County Surveyor's Comment _____



BASIS OF BEARINGS

THE BASIS OF BEARINGS FOR THIS SURVEY IS THE EAST LINE OF R.S. 12-8, S.J.C.R. SHOWN ON R.S. 12-8 AS "NORTH".

SCALE: 1" = 100'

LEGEND

- INDICATES SET 3/4" ϕ x 30" IRON PIPE TAGGED L.S. 4450
- INDICATES FOUND MONUMENT AS NOTED
- (M) INDICATES MEASURED ON THIS SURVEY
- S.F.N. INDICATES SEARCHED, FOUND NOTHING

REFERENCES

- (A) R.S. 12-8, S.J.C.R.
- (B) R.S. 29-122, S.J.C.R.

THE PURPOSE OF THIS SURVEY IS TO RETRACE MAP DATA AS SHOWN ON R.S. 12-8 AND TO RESET THE DESTROYED MONUMENTS. THIS CORNER RECORD MAP DOES NOT NECESSARILY REFLECT THE CURRENT PROPERTY LINES. THIS SURVEY DISCOVERED A MATHEMATICAL ERROR ON R.S. 12-8 AT THE NORTHEASTERLY CORNER OF THE PROPERTY [13.02(M) VS. 12.02(A)]

