


CORNER RECORD

Document Number CR-99-25  
County of San Joaquin, California

City of \_\_\_\_\_

Brief Legal Description Center of Section 21, T3N, R7E.  
PER P.M. 20-1



CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 10-21-99

COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Found bolt & washer stamped "LS 2239" in monument box at center of Section 21, T3N R7E, per PM 20-01. No attempt was made to verify that found monument is monument as noted in P.M. 20-01.

A description of the physical condition of the monument as found and as set or reset: Monument was in good condition & left as found. (Monument box was placed over in monument box during 1999 Alpine Road Resurfacing Project)

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 21 Oct, 1999.

Signed [Signature] R.C.E. Number 2334



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received NOVEMBER 5, 1999 and examined and filed December 3, 1999.

Signed [Signature] R.C.E. No. 21258

Title \_\_\_\_\_ County Surveyor



County Surveyor's Comment \_\_\_\_\_

(D.D. Sheet No. 16)

Jerry Vickett

