

CORNER RECORD

Document Number CR 11-157

City of RIPON County of SAN JOAQUIN, California

Brief Legal Description APPARENT 1/4 SECTION LINE, 12'± SOUTH FROM THE CENTER OF SECTION 34, T.2S., R.7E., M.D.B.&M.

NW 1/4	NE 1/4
SW 1/4	SE 1/4

SEC.34 T2S, R7E

Government Corner ☐ Control ☐
 Meander ☐ Property ☐
 Rancho ☐ Other ☒
 Date of Survey 08-03-2011

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 ☐ NAD83 ☐
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 ☐ NAVD88 ☐
 Meas. Units: Metric ☐ Imperial ☐

Corner — Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablished the corner:
FOUND 5/8" REBAR WITH CAP L.S. 5443 APPROXIMATELY 12'± SOUTH OF THE CENTER OF SECTION 34
T.2S., R.7E., M.D.B.&M. FOUND MONUMENT AS SHOWN ON RECORD OF SURVEY FILED IN BOOK 32
OF SURVEYS AT PAGE 186, SAN JOAQUIN COUNTY RECORDS.

A description of the physical condition of the monument as found and as set or reset: _____
MONUMENT IS IN AREA OF RECONSTRUCTION, SET TIES AS SHOWN ON PAGE 2.

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on AUGUST 3, 2011.

Signed [Signature] L.S. 6953



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received SEPTEMBER 9, 2011 and examined and filed OCTOBER 20, 2011.

Signed Thomas M. Gau P.L.S. or R.C.E. No. 26994

Title COUNTY SURVEYOR

County Surveyors Comment _____



