

CORNER RECORD

Document Number CR-11-192

City of RIPON County of SAN JOAQUIN, California

Brief Legal Description MONUMENT APPROXIMATELY 1162'± EAST ALONG THE SECTION LINE
FROM THE APPARENT SW CORNER OF SECTION 25, T.2S., R.7E., M.D.B.&M.

COORDINATES (Optional)

NW 1/4	NE 1/4
SW 1/4	SE 1/4

Government Corner ☐ Control ☐

Meander ☐ Property ☐

Rancho ☐ Other ☒

Date of Survey 10-26-2011

N. _____

E. _____

Zone _____ NAD27 ☐ NAD83 ☐

NAD83 Epoch _____

Elev. _____

Vert. Datum: NGVD29 ☐ NAVD88 ☐

Meas. Units: Metric ☐ Imperial ☐

SEC.25 T2S, R7E

Corner - Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablished the corner:

FOUND 1-1/2" IRON PIPE NOT TAGGED, APPROXIMATELY 1162'± EAST ALONG THE SECTION LINE

FROM THE APPARENT SW CORNER OF SECTION 25, T.2S., R.7E., M.D.B.&M. FOUND MONUMENT AS

SHOWN ON RECORD OF SURVEY FILED IN BOOK 13 OF SURVEYS AT PAGE 213, SAN JOAQUIN COUNTY
RECORDS.

A description of the physical condition of the monument as found and as set or reset: _____

MONUMENT IS IN AREA OF RECONSTRUCTION, SET TIES AS SHOWN ON PAGE 2.

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on NOVEMBER 11, 2011.

Signed [Signature] L.S. 6953

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received NOVEMBER 16, 2011 and examined and filed DECEMBER 12, 2011.

Signed Thomas M. Gau P.L.S. or R.C.E. No. 26994

Title COUNTY SURVEYOR

County Surveyors Comment _____



