


# CORNER RECORD

Document Number CR-12-434City of MANTECACounty of SAN JOAQUIN, CaliforniaBrief Legal Description NW 1/4, SEC 33, T1S, R7E, M.D.M. R.O.S. 31-200

## CORNER TYPE

Government Corner	<input type="checkbox"/>	Control	<input type="checkbox"/>
Meander	<input type="checkbox"/>	Property	<input type="checkbox"/>
Rancho	<input type="checkbox"/>	Other	<input checked="" type="checkbox"/>

Date of Survey MAY 9, 2012

## COORDINATES(Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27 ☐ NAD83 ☐  
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29 ☐ NADV88 ☐  
Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND SPIKE AND WASHER AT THE CENTERLINE INTERSECTION  
OF ALAMEDA STREET AND LINCOLN AVENUE PER R.O.S. 31-200.  
SET FOUR 2 FOOT SWING TIES FOR MONUMENT TO BE REMOVED  
AND REPLACED.

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on SEPTEMBER 4, 2012.Signed Michael L. Foulk P.L.S. or R.C.E. No.: 7803

## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received OCTOBER 25, 2012 and examinedand filed DECEMBER 13, 2012.Signed Jeff D. Lund P.L.S. or R.C.E. No.: 4440Title Asst. County Surveyor

County Surveyor's Comment THIS CORNER RECORD IS NOT IN COMPLIANCE  
WITH BOARD RULE 464(C) REGARDING SUBMITTAL WITHIN 90  
DAYS OF THE DATE OF SURVEY.



