


**CORNER RECORD**

DPD-3011 (Rev. 9/97) CT# 7541-4548-0

Document Number CR-13-220

City of \_\_\_\_\_

County of San Joaquin, CaliforniaBrief Legal Description Benchmark D 952

T3N, R7E, MDM

**CORNER TYPE**

Government Corner ☐ Control ☒  
 Meander ☐ Property ☐  
 Rancho ☐ Other ☐  
 Date of Survey November 29, 2012

**COORDINATES (Optional)**

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ NAD27 ☐ NAD83 ☐  
 NAD83 Epoch \_\_\_\_\_  
 Elevation 62.89  
 Vert. Datum: NGVD29 ☒ NAVD88 ☐  
 Meas. Units: Metric ☐ Imperial ☒

Corner - Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Benchmark D 952 (NGS PID JS1441) brass disk in concrete headwall, stamped D 952. References were set and elevated in  
accordance with NGS Bench Mark Reset instructions dated March 2001.

Adjusted level run and detailed descriptions of monument locations can be found in Field Book SR 1210-0106 on file at  
Caltrans Surveys, Bldg 4, 1976 Dr. Martin Luther King Jr Blvd, Stockton.

A description of the physical condition of the monument as found and as set or reset:

Found brass disk in concrete headwall, along the east side of State Highway 88, 0.1 mile south of Live Oak Road.

Corners set: 1" iron pipe with red plastic Caltrans cap.

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on November 29, 2012.

Signed Jill Van Houten P.L.S. or R.C.E. Number 7215

For the State of California  
 Department of Transportation

**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received June 18, 2013 and examined

and filed July 7, 2013.

Signed Thomas M. Gau P.L.S. or R.C.E. Number 26994

Title County Surveyor

County Surveyor's Comment \_\_\_\_\_



# CORNER RECORD

DPD-3011 (Rev. 3/13)

