CORNER RECORD

CR-13-316 Document Number City of UNINCORPORATED County of SAN JOAQUIN Brief Legal Description PARCEL B OF PARCEL MAP FILED IN BOOK 12 OF MAPS, PAGE 151 **CORNER TYPE** COORDINATES(Optional) Government Corner Control Meander Property Zone Rancho Other NAD83 Epoch Date of Survey October 3, 2013 T35, RSE, MDM NGVD29 NADV88 Vert. Datum: Imperial X Metric Meas, Units: Corner -Left as found Found and tagged Established Reestablished X Rebuilt | Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: MONUMENTS SHOWN ON PARCEL MAP 12 ~ 51, ALONG THE CENTERLINE OF DURHAM FERRY ROAD AS SHOWN ON SKETCH, PAGE 2. A description of the physical condition of the monument as found and as set or reset: SET 5/8"x24" REBAR & PLASTIC CAP STAMPED "LAMB, LS 6627" AS SHOWN ON SKETCH, PAGE 2. **SURVEYOR'S STATEMENT** This Corner Record was prepared by me or under my direction in conformance with No. LS6C27 OCTOBER 3rd the Land Surveyor's Act on? P.L.S. or R.C.E. No.: **COUNTY SURVEYOR'S STATEMENT** This Corner Record was received October 28 2013 and examined Hau P.L.S. of R.C.E. No.: 26994 Title County Surveyor **County Surveyor's Comment** No. 26994 EXP. 3-31-2015

