


# CORNER RECORD

Document Number CR-13-317  
City of UNINCORPORATED County of San Joaquin, California

Brief Legal Description Locating and resetting corners for Parcel A, Record of Survey, Book 24, Page 100



T 2 S, R 4 E, M 1 D M

## CORNER TYPE

Government Corner ☐ Control ☐  
Meander ☐ Property ☒  
Rancho ☐ Other ☐

Date of Survey December 16, 2010

## COORDINATES(Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27 ☐ NAD83 ☐  
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29 ☐ NADV88 ☐  
Meas. Units: Metric ☐ Imperial ☒

Corner - Left as found ☐ Found and tagged ☒ Established ☒ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found existing corner monuments along the northern line of the subject parcel, found the rebars with caps missing at some of the corners, see sketch page 2.

A description of the physical condition of the monument as found and as set or reset: Set new caps on the found rebars which were missing their caps, set new rebars and caps at the missing corners per the record locations.

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on December 29, 2010.

Signed Gary K. Lane P.L.S. or R.C.E. No.: PLS6627



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received October 28, 2013 and examined and filed November 17, 2013.

Signed Thomas M. Gau P.L.S. or R.C.E. No.: 26994

Title County Surveyor

## County Surveyor's Comment

This corner record is not in compliance with Board Rule 464(c) regarding submittal within 90 days from date of survey.

