
## CORNER RECORD

	Document Number
City ofLATHROP	County of <u>SAN JOAQUIN</u> , California
Brief Legal Description MONUMENT IN D'ARCY PARKWAY	APPROXIMATELY 2349'± SOUTHEAST OF MURPHY
PARKWAY. LOCATED IN SECTION	35, T.1S, R.6E, M.D.B.&M.
CORNER TYPE	COORDINATES (Optional)
NW NE	N
1/4 1/4 Government Corner Contri	
SW SE Rancho Other	
1/4 SE Rancho Other	NAD83 Epoch
	Elev.  —2013 Vert. Datum: NVGD29 NVGD88
SEC. 35 T.1S, R.6E Date of Survey10-23	—2013 Vert. Datum: NVGD29 NVGD88 Meas. Units: Metric Imperial   ✓
	meds. Offits. Metric Imperior 23
Corner- Left as found 🔀 Found and tagged 🗌	Established Reestablished Rebuilt
Identification and type of corner found: Evidence used to iden	tify or procedure used to establish or reestablish the corner:
FOUND NECK OF BROKEN BRASS DISK IN MONUMENT N	VELL, IN D'ARCY PARKWAY AT APPROXIMATELY 2349'±
SOUTHEAST OF MURPHY PARKWAY. LOCATED IN SECTION	35, T.1S, R.6E, M.D.B.&M. FOUND MONUMENT AS
SHOWN ON RECORD MAP FILED IN BOOK 33 OF MAPS	· · · · · · · · · · · · · · · · · · ·
9	
n	
A description of the physical condition of the monument as fo	und and as set or reset:
MONUMENT IS IN AREA OF RECONSTRUCTION, SET TIES	AS SHOWN ON PAGE 2.
SURVEYOR'S STATEMENT	in conformance with
This Corner Record was prepared by me or under my direction	in conformance with
the Land Surveyors' Act onNOVEMBER 12,,	0017
the Land Surveyors Act on	
	\\
Signed P.L.S. or R.C.E. 1	lumber 6953 OF CALIFORN
COUNTY SURVEYOR'S STATEME	NT
This Corner Record was received November 20	2013 and examined PROFESSIONAL
and filed December 1, 2013	and examined PROFESSIONAL REPORTS OF THE PROFESSIONAL REPO
Signed Thom M. Have P.L.S. or R.C.E.	No: 26994
Title County Surveyor	(원 No. 26994
County Surveyor's Comment	11 1
Standy Standard Standard	
	STATE CIVIL THE



Page 2 of 2