## **CORNER RECORD**

OUTINEIT INECORD	Document Number CR-14-309
City of MANTECA	County of SAN JOAQUIN, California
Brief Legal Description MONUMENT IN LOUISE AVENUE	
APPEARS TO BE THE SOUTH Q	UARTER CORNER OF SECTION 30, T.1S, R.7E, M.D.B.&M.
CORNER TYPE	COORDINATES (Optional)
NW NE Government Corner Corn	itrol
Meander Pro	Perty
SW SE Rancho Oth	
1/4 1/4	Elev.
SEC. 30 T.1S, R.7E Date of Survey11-	12−2014 Vert. Datum: NVGD29 NVGD88 Meas. Units: Metric Imperial 🔀
Corner— Left as found 🔀 Found and tagged 🗌	Established Reestablished Rebuilt
Identification and type of corner found: Evidence used to id	entify or procedure used to establish or reestablish the corner:
FOUND RAILROAD SPIKE NOT TAGGED, IN LOUISE AVEN	NUE APPROXIMATELY 230'± WEST OF PHILLIPS DRIVE
APPEARS TO BE THE SOUTH QUARTER CORNER OF SE	
AS SHOWN ON RECORD OF SURVEY FILED IN BOOK 2	7 OF SURVEYS AT PAGE 100, SAN JOAQUIN COUNTY
RECORDS.	
A description of the physical condition of the monument as	found and as set or reset:
MONUMENT IS IN AREA OF RECONSTRUCTION, SET TIES AS SHOWN ON PAGE 2.	
SURVEYOR'S STATEMENT	LAMP
This Corner Record was prepared by me or under my directic	on in conformance with
	W / III
the Edito Surveyors Act on	
	N□. 6953
SignedP.L.S. or <del>R.C.E.</del>	Number 6953 CALTIFICATION CALTIFICATION OF CALTIFICATION
P.L.S. or <del>K.C.L.</del>	Number 6953
COUNTY SURVEYOR'S STATEM	ENT WALLAND
This Corner Record was received	ZOIA and examined WARREN D SMITH
and filed December 24 2014	SMITH OR
MA/2 P 3	
Title Acting County Surveyor	No: 4842
County Surveyor's Comment	CAL
•	

