


CORNER RECORD

Document Number CR 15-39

City of _____

County of San Joaquin, California

Brief Legal Description Southwest Corner of Section 19, T.3N., R.6E., M.D.B. & M.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other

COORDINATES(Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NADV88
 Meas. Units: Metric Imperial

Sec. 19, T.3N., R.6E.,
 M.D.B. & M.

Date of Survey November 2, 2001

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

See Sheet 2

A description of the physical condition of the monument as found and as set or reset: _____

See Sheet 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on Mar. 18, 2015.

Signed Michael L. Quaratoro P.L.S. or R.C.E. No.: L.S. 4450



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received March 18, 2015 and examined and filed April 6, 2015.

Signed Warren D. Smith P.L.S. or R.C.E. No.: 4842

Title Acting County Surveyor

County Surveyor's Comment _____





NOT TO SCALE
2008-146

THORNTON ROAD

RS 7-9

SEC. 24

SEC. 19

19.2'(M)

7.65'(M)

SEC. 25
T.3N., R.5E.,

SEC. 30
T.3N., R.6E.,

SET SPIKE AND WASHER
STAMPED L.S. 4450 ON
POWER POLE

FOUND SAN JOAQUIN COUNTY
BENCHMARK "Y-15"

FD. 18" LONG ROD W/SQUARE
NUT, REMOVED AND REPLACED
WITH 2" IRON PIPE W/BRASS
CAP STAMPED L.S. 4450, SET IN
MORTAR ABOUT 18" DEEP, 1 LEFT
WOOD POST REMAINS INTACT