

CORNER RECORD


DPD-3011 (Rev. 9/97) CT# 7541-4548-0

Document Number CR-16-122

City of _____

County of San Joaquin, California

Brief Legal Description Centerline of State Route 4 at the intersection with Inland Drive, Sec's 14 & 23 TIN R5E



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey October 28, 2015

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elevation _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

"A": Found 1" square bolt with washer in a/c pavement. (14-S-11 S.J.C.R.).

"B": Found 1" square bolt with washer in a/c pavement. (14-S-11 S.J.C.R.).

A description of the physical condition of the monument as found and as set or reset:

"A": Monument was disturbed by the rehabilitation construction and was replaced with an 1" iron pipe with yellow plastic cap stamped "Calif DOT" in a monument well.

"B": Found 1" square bolt with washer in good condition. Monument well was installed at the new pavement surface.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on December 10, 2015

Signed [Signature] P.L.S. or R.C.E. Number 8415

For the State of California
Department of Transportation



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received February 10, 2016 and examined

and filed February 29, 2016

Signed [Signature] P.L.S. or R.C.E. Number 4842

Title Acting County Surveyor



County Surveyor's Comment _____

