

CORNER RECORD

DPD-3011 (Rev. 9/97) CT# 7541-4548-0

Document Number CR-16-123

City of _____ County of San Joaquin, California

Brief Legal Description Sec's 13 & 24 T1N R5E, and Sec's 18 & 19 T1N R6E

CORNER TYPE		COORDINATES (Optional)	
Government Corner	<input checked="" type="checkbox"/>	Control	<input type="checkbox"/>
Meander	<input type="checkbox"/>	Property	<input type="checkbox"/>
Rancho	<input type="checkbox"/>	Other	<input type="checkbox"/>
Date of Survey	<u>October 28, 2015</u>		
		N. _____	
		E. _____	
		Zone _____	NAD27 <input type="checkbox"/> NAD83 <input type="checkbox"/>
		NAD83 Epoch _____	
		Elevation _____	
		Vert. Datum: NGVD29 <input type="checkbox"/>	NAVD88 <input type="checkbox"/>
		Meas. Units: Metric <input type="checkbox"/>	Imperial <input checked="" type="checkbox"/>

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found 1" square bolt with washer in a/c pavement. (3-PM-032 S.J.C.R.).

A description of the physical condition of the monument as found and as set or reset:
Monument was destroyed by the rehabilitation construction and was replaced with a 2 1/4" brass disk stamped "Calif Dept of Transportation" in a monument well.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on December 10, 2015.
 Signed [Signature] P.L.S. or R.C.E. Number 8415
 For the State of California
 Department of Transportation



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received February 10, 2016 and examined and filed February 29, 2016.
 Signed [Signature] P.L.S. or R.C.E. Number 4842
 Title Acting County Surveyor



County Surveyor's Comment _____

