

CORNER RECORD


DPD-3011 (Rev. 9/97) CT# 7541-4548-0

Document Number CR-16-125

City of Stockton

County of San Joaquin, California

Brief Legal Description Sec's 18 & 19 T1N R6E



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey October 28, 2015

COORDINATES (Optional)

N. _____
E. _____
Zone NAD27 NAD83
NAD83 Epoch _____
Elevation _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found 1" square bolt with washer in a/c pavement. (3-PM-032 S.J.C.R.).

A description of the physical condition of the monument as found and as set or reset:
Monument was destroyed by the rehabilitation construction and was replaced with a 2 1/4" brass disk stamped "Calif Dept of Transportation" in a monument well.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on December 10, 2015

Signed [Signature] P.L.S. or R.C.E. Number 8415

For the State of California
Department of Transportation



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received February 10, 2016 and examined

and filed February 29, 2016

Signed [Signature] P.L.S. or R.C.E. Number 4842

Title Acting County Surveyor



County Surveyor's Comment _____

