CORNER RECORD City of Vernalis	San Joaquin		Number
Brief Legal Description West 1/4 Corner of Section 35, T3S, R6E, MDB&M			
-35 - Me	CORNER TYPE vernment Corner ☑ Contro ander □ Proper ncho □ Other te of Survey <u>08-29-201</u>	ty 🗆	COORDINATES (Optional) N E Zone NAD27 □ NAD83 □ NAD83 Epoch Elev Vert. Datum: NGVD29 □ NAVD88 □ Meas. Units: Metric □ Imperial □
Corner – Left as found	¶ Found and tagged □ Es	tablished	Reestablished Rebuilt
Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Found 3/4" Iron Pin at Intersection of SR33 and Welty Rd. per Record of Survey 33-48 filed in SJCR. A description of the physical condition of the monument as found and as set or reset: Monument found in good condition, Top of Iron Pin mushroomed. Down 0.85' below pavement in 1 foot diameter monument well.			
SURVE	EYOR'S STATEMENT		STONAL LAND SU
This Corner Record was prepared to the Land Surveyor's Act on	August 29,2 P.L.S or R.C.E. No.	2016	11516 91211
This Corner Record was received September 8, 2016			
and examined and filedSept	P.L.S OF R.C.E. No. 484	+2	WARREN D SMITH No 4842 W OF CALIFORNIA

