


# CORNER RECORD

Agency Index CR-17-133  
Document Number \_\_\_\_\_

City of Tracy County of San Joaquin, California  
Brief Legal Description Monument at intersection of MacArthur Drive and Arbor Avenue.



### CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other

Date of Survey March 24, 2017

### COORDINATES (Optional)

N. \_\_\_\_\_ E. \_\_\_\_\_

Elevation \_\_\_\_\_

Units Metric  U.S. Survey Foot

Horizontal Datum \_\_\_\_\_

Zone \_\_\_\_\_ Epoch Date \_\_\_\_\_

Vertical Datum \_\_\_\_\_

Complies with Public Resources Code §§8801-8819

Complies with Public Resources Code §§8890-8902

PLS Act Ref.:  8765(d)  8771  8773  Other:

Corner/Monument:  Left as found  Established  Rebuilt  Pre-Construction  
 Found and tagged  Reestablished  Referenced  Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

**Found 2" brass disk with punch stamped LS4479 inside monument well.**

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on March 28, 2017

Signed *Richard J. Hickenbottom* P.L.S. or R.C.E. No. 8654



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received April 17, 2017

and examined and filed May 18, 2017

Signed *Warren D. Smith* P.L.S. or R.C.E. No. 4842

Title County Surveyor

County Surveyor's Comment



**LEGEND**

- ⊗ SET NAIL W/ TAG "LS8654"
- SET IRON PIPE W/ PLUG "LS8654"
- ⊙ MONUMENT
- PP POWER POLE
- GLM GAS LINE MARKER
- TB TELEPHONE BOX
- EDGE OF PAVEMENT



Scale 1" = 30'

