CORNER RECORD

CR-17-142 Agency Index Document Number SAN JOAQUIN TRACY County of City of CENTER 1/4 CORNER OF SECTION 6, T3S, R5E, MDM. Brief Legal Description COORDINATES (Optional) **CORNER TYPE** E. Government Corner Control Elevation X U.S. Survey Foot Property Units Meander X Other Rancho Horizontal Datum Epoch Date Date of Survey Vertical Datum May 2, 2017 Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 Other: X 8771 8773 PLS Act Ref.: 8765(d) Established Pre-Construction Rebuilt Left as found Corner/ Monument: Post-Construction Referenced Reestablished Found and tagged Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 3/4" IRON PIPE AT THE CENTER 1/4 CORNER OF SECTION 6, T3S, R5E, MDM PER PARCEL MAP (6 PM 193). DESTROYED DURING CONSTRCTION. REPLACED WITH NAIL AND TAG, LS 8164. SURVEYOR'S STATEMENT No. 8164 This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on May 2, 2017 P.L.S. or R.C.E. No. PLS 8164 Signed COUNTY SURVEYOR'S STATEMENT May 4, 2017 This Corner Record was received and examined and filed P.L.S. or R.C.E. No. 4842 Signed No 4842 County Surveyor

Page 1 of 2

County Surveyor's Comment

Title

Document Number	 Agency Index		
		÷	
			·
•			
	•		