CORNER RECORD	Document Number <u>CR-17-157</u>
City of TRACY	
Brief Legal Description 5.W. 1/4 of SECTION 32	
— — 3 2 — — Meander □ Pro	coordinates (Optional) N. E. Operty Zone NAD27 □ NAD83 □ NAD83 Epoch Her □ Elev. Vert. Datum: NGVD29 □ NAVD88 □ Meas. Units: Metric □ Imperial
TZS, RSE, MPM	model office. Interior El Importar pa
Corner — Left as found ☐ Found and tagged ☐	Established 🔼 Reestablished 🗆 Rebuilt 🗆
Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: MONUMENTS COULD NOT BE SET IN ACCORDANCE WITH TRACT 3779, RECORDED JULY 3, 2013, IN BOOK 41 of MAPS AND PLATS AT PAGE 94 A description of the physical condition of the monument as found and as set or reset: MONUMENTS FOR THE	
FRONT CORNERS OF 155/156, 197/	
SET DUE TO THE CONSTRUCTION OF THE SIDEWALK. FRONT CORNERS	
WERE SET ON A PROLONGATION OF THE SIDE LOT LINE, SEE REVERSE.	
	•
SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction the Land Surveyor's Act on DECEMBER 2 Signed P.L.S or R.C.E. No	
COUNTY SURVEYOR'S STATEMENT	
This Corner Record was received	2017
This Corner Record was received January 21, 2017 and examined and filed Jone 20, 2017 Signed Mark D. January 21, 2017 P.L.S or R.C.E. No. 4842	
Title County Surveyor	OF CALIFORNIE
County Surveyor's Comment	

