## **CORNER RECORD**

Document Number County of San Joaquin Brief Legal Description replacement monument for NGS BM F 473 - PID HS0432, Sec 24/T1N/R5E **COORDINATES (Optional) CORNER TYPE** N. 2161070+/-E. 6309235+/-1.30(NAVD88), -1.13(NGVD29) Government Corner Elevation Control X U.S. Survey Foot Meander Property Units Metric Rancho Other NAD83 Horizontal Datum N/A **Epoch Date** Zone Date of Survey August 1, 2017 Vertical Datum NAVD 88/NGVD29 Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 Other: 8765(d) 8771 8773 PLS Act Ref.: Established Pre-Construction Left as found Rebuilt Corner/ Monument: Post-Construction Found and tagged Reestablished Referenced Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): Benchmark F473 Reset 197? was destroyed during reconstruction of headwall in 2015+/-. A new Brass cap was set in the new headwall on July 31, 2017 and new elevations established. Brass Cap F473 set 1951......El= -1.083 (NGVD29), L21067, NGS rerun levels, pg 25 0f 54, 1967. Brass Cap F473 Reset 197? ......El= -0.87 (NGVD29) per Caltrans bench run SR970848, 1998 SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with SPENCER the Professional Land Surveyors' Act on August 11, 2017 LS 6406 Signed **COUNTY SURVEYOR'S STATEMENT** August 16, 2017 This Corner Record was received September 8, 2017. and examined and filed SMITH P.L.S. or R.C.E. No. 4842 Signed No 4842 Title County Surveyor County Surveyor's Comment

CR-17-269

Agency Index



