## **CORNER RECORD**

Agency Index \_\_CR-19-45 Document Number \_\_\_\_\_ County of SAN JOAQUIN , California City of STOCKTON Brief Legal Description MONUMENT NEAR THE SOUTHEAST CORNER OF PARCEL 1, PM 22-19 COORDINATES (Optional) **CORNER TYPE** Elevation \_ Control Metric U.S. Survey Foot M Property Meander T2N/R6E Horizontal Datum \_ Rancho Zone \_\_\_\_\_ Epoch Date \_\_\_ SEC Vertical Datum: \_ Date of Survey 2019-01-23 Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 8773 8765(d) PLS Act Ref .:  $\bowtie$ Pre-Construction Corner/ Left as found Established Rebuilt Reestablished Referenced Post-Construction Found and tagged Monument: Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 3/4" IRON PIPE, NO TAG, NEAR THE SOUTHEAST CORNER OF PARCEL 1 AS SHOWN ON THE PARCEL MAP FILED IN BOOK 22 OF PARCEL MAPS, PAGE 19, SAN JOAQUIN COUNTY RECORDS, NEAR THE INTERSECTION OF HAMMER LANE AND THE 100' WIDE EAST BAY MUNICIPAL UTILITIES DISTRICT (E.B.M.U.D.) RIGHT-OF-WAY. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyor's Act on No. 8366 P.L.S. or R.C.E. No.: \_\_ Signed \_ Exp. 12-31-2019OF CALIF COUNTY SURVEYOR'S STATEMENT April 17 This Corner Record was received and filed P.L.S. or R.C.E. No.: 8657 County Surveyor County Surveyor's Comment \_\_\_