

CORNER RECORD

Agency Index CR-19-120


Document Number _____

City of Stockton County of San Joaquin, California

Brief Legal Description CENTERLINE OF TAM O'SHANTER DRIVE, PER BOOK 25 OF MAPS AND PLATS, PAGE 108.

CORNER TYPE

COORDINATES (Optional)



- Government Corner
- Meander
- Rancho
- Control
- Property
- Other

Date of Survey July 19, 2019

N. _____ E. _____

Elevation _____

Units Metric U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

Complies with Public Resources Code §§8801-8819

Complies with Public Resources Code §§8890-8902

T.2N., R.6E., M.D.B.&M.

PLS Act Ref.: 8765(d) 8771 8773 Other:

Corner/Monument: Left as found Established Rebuilt Pre-Construction

Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

Found 1" iron rod, down 0.6', in a monument well along the centerline of Tam O'Shanter Drive, taken as marking the southerly end of a 1,000' radius curve, west of the most southerly corner of Lot 6 per map of Tract No. 1695, Hammertown Unit No. 4, filed in Book 25 of Maps and Plats, at Page 108, San Joaquin County Records.

Set new ties; see reverse for details.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Professional Land Surveyors' Act on September 18, 2019.

Signed *Scott J. Roberts* (P.L.S.) or R.C.E. No. 9235



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received September 19, 2019

and examined and filed October 3, 2019

Signed *James E. Hart* P.L.S. or R.C.E. No. 8657

Title County Surveyor

County Surveyor's Comment



LEGEND:

MONUMENT TIE LINE	---
CURB	—
MP	MAPS AND PLATS
LOT LINE	---
CENTERLINE	---

REFERENCE:

(R1) 25-MP-108, SAN JOAQUIN COUNTY RECORDS

