## **CORNER RECORD**

Document Number \_ City of STOCKTON County of SAN JOAQUIN \_\_\_\_\_, California Brief Legal Description MONUMENTS ALONG THE SOUTH LINE OF PARCEL 4, PM 22-19 **CORNER TYPE** COORDINATES (Optional) Flevation Government Corner Control Metric U.S. Survey Foot Units X Property Meander T2N/R6E Horizontal Datum \_ Rancho Other 13 Zone \_\_\_\_\_ Epoch Date \_ SEC Vertical Datum: \_\_ Date of Survey 2019-01-23 Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §\$8890-8902 PLS Act Ref .: 8765(d) X 8771 8773 Other: Corner/ Left as found Established Rebuilt Pre-Construction Found and tagged Reestablished Post-Construction Monument: Referenced Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 2 - 3/4" IRON PIPES, NO TAG, ALONG THE SOUTH LINE OF PARCEL 4 AS SHOWN ON THE PARCEL MAP FILED IN BOOK 22 OF PARCEL MAPS, PAGE 19. SAN JOAQUIN COUNTY RECORDS, NEAR THE INTERSECTION OF HAMMER LANE AND HOLMAN ROAD. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyor's Act on No. 8366 P.L.S. or R.C.E. No.: Signed Exp. 12-31-2019COUNTY SURVEYOR'S STATEMENT April 13, 2020 and examined This Corner Record was received County Surveyor's Comment \_\_\_

