CORNER RECORD

Document Number San Joaquin County of Stockton Found monument as noted, referenced and left as found. Brief Legal Description **COORDINATES (Optional) CORNER TYPE** E. Control Elevation Government Corner U.S. Survey Foot Metric Property Units Meander Other Rancho **Horizontal Datum** Zone Epoch Date Date of Survey September 12, 2020 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 X 8771 8773 Other: 8765(d) PLS Act Ref.: **Pre-Construction** Left as found Established Rebuilt Corner/ Monument: Referenced Post-Construction Found and tagged Reestablished Narrative of corner identified and monument as found, set, reset, replaced, or removed: ✓ See sheet #2 for description(s): Found a PK Nail in the asphalt of Miner Ave, near the intersection of Miner Ave and Hunter St. Set four (4) reference points, as noted on the reverse, outside of the construction limits. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on January 31, 2022 LANDRUM LS 5837 P.L.S. or R.C.E. No. Signed **COUNTY SURVEYOR'S STATEMENT** This Corner Record was received and examined and filed P.L.S. of R.C.E. No. 8657 Signed No. 865 Title **County Surveyor's Comment**

Agency Index

Page 1 of 2