CORNER RECORD

Document Number San Joaquin Stockton County of Found monument as noted, referenced and left as found. Brief Legal Description **COORDINATES (Optional) CORNER TYPE** Elevation Government Corner Control U.S. Survey Foot Metric X Property Meander Units Other Horizontal Datum Rancho Epoch Date Date of Survey September 12, 2020 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 Other: 8771 8773 8765(d) PLS Act Ref.: **Pre-Construction** Rebuilt Established Left as found Corner/ Post-Construction Monument: Referenced Found and tagged Reestablished Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): Found a lead and tag, stamped LS 4450, in the concrete sidewalk near the southwest curb return of Miner Ave and Sutter St. Set four (4) reference points, as noted on the reverse, outside of the construction limits. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with LANDRUM the Professional Land Surveyors' Act on January 31, 2022 LS 5837 Signed **COUNTY SURVEYOR'S STATEMENT** February 1, 2022 This Corner Record was received February 14, 2022.

P.L.S. OFR.O.E. No. 8657 and examined and filed Signed Title **County Surveyor's Comment**

CR-22-045

Agency Index