


CORNER RECORD

Agency Index CR-23-251
Document Number _____

City of _____ County of San Joaquin, California
Brief Legal Description _____ NGS Benchmark BM No. 3 Reset

CORNER TYPE



- Government Corner
- Meander
- Rancho
- Control
- Property
- Other

Date of Survey October 17, 2023

Sec. 1, T.1S., R.5E.,
M.D.B. & M.

COORDINATES (Optional)

N. 2143034 Ft. E. 6306611 Ft.
Elevation _____
Units Metric U.S. Survey Foot
Horizontal Datum NAD83
Zone SPC-3 Epoch Date _____
Vertical Datum _____
 Complies with Public Resources Code §§8801-8819
 Complies with Public Resources Code §§8890-8902

- PLS Act Ref.: 8765(d) 8771 8773 Other:
- Corner/Monument: Left as found Established Rebuilt Pre-Construction
 Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

SPC - 3 coordinates listed are the result of Post Processing (differentially correcting) data that was logged from an Ashtech Mobile Mapper 10 handheld GPS receiver and are in the sub-meter accuracy range.

The Grid coordinate is provided for the purpose of facilitating locating the monument

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 10.23.2023
Signed Michael L. Quartroun P.L.S. or R.C.E. No. L.S. 4450



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received October 24, 2023
and examined and filed November 7, 2023
Signed James E. Hart P.L.S. or R.C.E. No. 8657
Title County Surveyor



County Surveyor's Comment



Northwesterly corner of the Howard Road Bridge across Middle River.