CORNER RECORD

Agency Index

CR-25-191

Document Number Stockton County of _____ , California San Joaquin City of Lots 552, 571, 572, 573, M&P 24-59 Brief Legal Description **CORNER TYPE COORDINATES (Optional)** ____E. ____ Government Corner Elevation Control U.S. Survey Foot Meander Property Units Metric Other Rancho Horizontal Datum Zone Epoch Date Date of Survey May 1, 2025 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 PLS Act Ref.: 8765(d) **X** 8771 8773 Other: Left as found Established Rebuilt Pre-Construction Corner/ Monument: Found and tagged Reestablished Referenced X Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on May 2, 2025 P.L.S. or R.C.E. No. _____PLS 7889 Signed **COUNTY SURVEYOR'S STATEMENT** This Corner Record was received and examined and filed No. 8657

BPELSG-2016 Page 1 of 2

County Surveyor's Comment

LEGEND:


S:\Projects\2024\24055-01\3_Drawings\24055-01_HC.dwg 05/02/25 1.49pm-CARTER-XREFS:

M&P MAPS & PLATS, VOLUME AND PAGE, SAN JOAQUIN COUNTY RECORDS

- FOUND 3/4" IRON PIN TAGGED
 "R.C.E. 15831" IN MONUMENT BOX
- FOUND CHISELED CROSS PER CORNER RECORD 25-041, SAN JOAQUIN COUNTY SURVEYOR'S RECORDS

DESCRIPTION:

THIS CORNER RECORD IS FOR THE PURPOSE OF MONUMENT PRESERVATION. REFERENCES WERE FOUND AND/OR SET FOR FOUND MONUMENTS AS NOTED ON DIAGRAM. NO BOUNDARY ANALYSIS WAS PERFORMED. THIS CORNER RECORD DOES NOT VERIFY THE MONUMENT(S) TO BE IN THE CORRECT POSITION.



Page 2 of 2