## **CORNER RECORD**

CR-25-203 Agency Index **Document Number** City of County of San Joaquin , California Brief Legal Description A Portion of the N.E. 1/4 of Section 33, T.2 N., R.8 E. **CORNER TYPE COORDINATES (Optional)** N. Government Corner Control Elevation Meander Property Units U.S. Survey Foot Metric Rancho Other Horizontal Datum Zone Epoch Date Date of Survey May 6, 2025 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 PLS Act Ref.: 8765(d) **X** 8771 8773 Other: Left as found Established Pre-Construction Rebuilt Corner/ Monument: Found and tagged Reestablished X Referenced X Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on May 6, 2025 PLS 7889 Signed P.L.S. or R.C.E. No. **COUNTY SURVEYOR'S STATEMENT** May 30, 2025

June 5, 2025

P.L.S. OFR.C.E. No. 8657 This Corner Record was received and examined and filed Signed No. 8657 Title

**County Surveyor's Comment** 

## LEGEND:

R.S. RECORD OF SURVEY, BOOK AND PAGE, SAN

JOAQUIN COUNTY RECORDS

SEC. SECTION FD FOUND

 FOUND MONUMENT AS NOTED PER CORNER RECORD 24-385, SAN JOAQUIN COUNTY SURVEYOR'S RECORDS

FOUND MONUMENT IN MONUMENT WELL AS NOTED PER CORNER RECORD 24-385, SAN JOAQUIN COUNTY SURVEYOR'S RECORDS


## **DESCRIPTION:**

THIS CORNER RECORD IS FOR THE PURPOSE OF MONUMENT PRESERVATION. REFERENCES WERE SET FOR FOUND MONUMENTS AS NOTED ON DIAGRAM. NO BOUNDARY ANALYSIS WAS PERFORMED. THIS CORNER RECORD DOES NOT VERIFY THE MONUMENT(S) TO BE IN THE CORRECT POSITION.



**(•)** 

LIMITS OF CONSTRUCTION AREA



51.91'

264.18'

5230.11' 5010.21'

S:\Projects\2024\24015\3\_Drawings\24015\_CR dwg 05/08/25 10:33am-CARTER-XREFS: 24015\_HCdwg

BS-O-FS

A-C-B

A-D-B

144°34'21"

173°04'38"