


# CORNER RECORD

Agency Index

CR-26-250

Document Number

City of Tracy County of San Joaquin, California  
Brief Legal Description Monument at South Quarter Corner of Section 26

**CORNER TYPE****COORDINATES (Optional)**

- |                                                       |                                   |
|-------------------------------------------------------|-----------------------------------|
| <input checked="" type="checkbox"/> Government Corner | <input type="checkbox"/> Control  |
| <input type="checkbox"/> Meander                      | <input type="checkbox"/> Property |
| <input type="checkbox"/> Rancho                       | <input type="checkbox"/> Other    |

Date of Survey June 10, 2026

N. \_\_\_\_\_ E. \_\_\_\_\_

Elevation \_\_\_\_\_

Units ☐ Metric ☒ U.S. Survey FootHorizontal Datum NAD83Zone 3 Epoch Date \_\_\_\_\_

Vertical Datum \_\_\_\_\_

☐ Complies with Public Resources Code §§8801-8819☐ Complies with Public Resources Code §§8890-8902

SEC.26, T2S, R4E MDB&amp;M

|                      |                                                   |                                          |                                     |                                                      |
|----------------------|---------------------------------------------------|------------------------------------------|-------------------------------------|------------------------------------------------------|
| PLS Act Ref.:        | <input type="checkbox"/> 8765(d)                  | <input checked="" type="checkbox"/> 8771 | <input type="checkbox"/> 8773       | <input type="checkbox"/> Other:                      |
| Corner/<br>Monument: | <input checked="" type="checkbox"/> Left as found | <input type="checkbox"/> Established     | <input type="checkbox"/> Rebuilt    | <input checked="" type="checkbox"/> Pre-Construction |
|                      | <input type="checkbox"/> Found and tagged         | <input type="checkbox"/> Reestablished   | <input type="checkbox"/> Referenced | <input type="checkbox"/> Post-Construction           |

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

☐ See sheet #2 for description(s):

Monument at South Quarter Corner of Section 26, as shown on the Record of Survey filed for record on July 17, 2017, in Book 39 of Surveys at Page 23, San Joaquin County Records.

Said monument is in danger of being disturbed by construction and is described as follows:  
2 inch brass disk in monument well, not stamped

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on July 22, 2026Signed Garry K. Lamb (P.L.S. or R.C.E. No. PLS 6627)**COUNTY SURVEYOR'S STATEMENT**


This Corner Record was received

and examined and filed

Signed Robert L. Borsdorf III P.L.S. or R.C.E. No. 9728Title County Surveyor

County Surveyor's Comment





0 500' 1000' 2000'  
Scale 1" = 1000'

