



MEMORANDUM

To: Duncan Jones (San Joaquin Parks and Recreation)
From: Alvin Yee (Siegfried)
cc: Bill Roach (Siegfried)
Date: December 22, 2015
Re: Woodbridge Wilderness Area Master Plan Revisions

Duncan,

Below is a list of revisions made by section to the Woodbridge Wilderness Area Master Plan draft:

1. Page numbers have been modified so that each map counts as a single page.
2. Page 5 – Mention of river access has been added (Section 1.1) and refers to California Code now referenced in Section 1.5 – Existing Policies.
3. Page 11 and page 33 (moved to page 35) - Extra gate has been removed from maps.
4. Page 12 - Eastern fire break trail has been adjusted to connect with the defensible space.
5. Page 15 - Specific U.S. Architectural Barriers Act section that requires improvements to comply with Outdoor Guidelines should federal funding be used has been added (Section 1.5).
6. Page 21 (moved to page 22) - Note regarding sign-in no longer necessary has been added to the section (Section 3.1).
7. Page 22 – Volunteer duties have been updated to include interpretive services (Section 3.1.A.4.)
8. Page 22 – Section on overlapping staff shifts has been added to Peak Season (Section 3.1.B.1.b.).
9. Pages 22 and 23 – Paragraph numbering has been corrected.
10. Page 23 (moved to page 24) – List of improvements required to construct dry stand pipe has been included (Section 3.2.C.1.). Typical section has been updated and moved to page 29 and improvement description includes reference to the diagram. Cost estimate has been modified to incorporate berm improvements.
11. Page 23 – Section on address placards has been separated from the dry standpipe subject (Section 3.2.C.2.).
12. Page 26 – High winds has been added to Closures Due to Hazards Section (Section 3.3.C.).

Stockton
3244 Brookside Rd., Ste. 100
Stockton, CA 95219
t: 209.943.2021 f: 209.942.0214

San Jose
111 N. Market St., Ste. 300
San Jose, CA 95113
t: 408.754.0121

Sacramento
111 Scripps Drive
Sacramento, CA 95825
t: 916.520.277

MEMORANDUM

Project Description
Location

Page 2 of 2



13. Page 28 and 29 – Diagram from page 48 has been moved to page 29. Top width has been shown as variable, access road at bottom of slope, and slope down from top of berm to property line.
14. Page 29 (moved to page 30) – Sentence has been completed (Section 3.5.C.2.).
15. Page 30-31 (comment addressed on page 32) – Section on allowing power equipment has been added (Section 3.6.B.1.e.).
16. Page 31 (moved to page 32) – Boardwalk image has been replaced with photo showing boards perpendicular to path of travel as stated in the master plan.
17. Page 31 (moved to page 33) – Boardwalk materials have been addressed. Exact specification will depend on desired maintenance and other environmental implications (Section 3.6.B.3.a.2j).
18. Page 33, Map 3.1 (moved to page 35) – Water access locations have been updated to provide access at all existing locations. Master plan has been modified to incorporate erosion control measures at each location (Section 3.7.B.2.).
19. Page 35 - Boulder reinforced slope with native planting has been added to river access section (Section 3.7.B.2.a.)
20. Page 35 (moved to page 36) – River access closure section has been removed and has been replaced with erosion control measures (Section 3.7.B.2.).
21. Page 37 (addressed in Appendix M) – County staff costs have been incorporated into Appendix M.
22. Page 37 (moved to page 38) – Closing tasks have been modified (3.7.C.2.)
23. Page 39 (moved to page 40) - Replacement for existing turf-block paver has been replaced with a permeable type paver that supports both vehicular and accessible pedestrian access. (3.10.B.1.b.)
24. Page 39 (moved to page 40) - Reference to replacement of entry gate has been removed.
25. Page 41 (moved to page 42) - Reference to an enclosed toilet facility has been removed along with accompanying images.
26. Page 45 (moved to page 43) – Map has been modified to show classroom to the west of the central spine. Restoration symbol has been moved to more clearly depict restoration along berm.
27. Page 42 – 500' requirement for bench locations has been removed.
28. Page 42 - Manufactured benches has been noted as being discouraged and should not be used.
29. Page 43 – Drinking fountain pictures have been moved to page 42, closer to drinking fountain section.
30. Page 48 (addressed on page 47) – Section regarding removing illegal encroachments has been added (3.14.A.5.).
31. Page 48-48 (addressed on page 48) – Defensible space planting now references Section 3.5 Bank Stability/Erosion Control. Referenced section has been updated to reference both new Appendices K (Why 100 Feet?) and L (Defensible Space Landscaping in the Urban/Wildlife Interface).

Stockton

3244 Brookside Rd., Ste. 100
Stockton, CA 95219
t: 209.943.2021 f: 209.942.0214

San Jose

111 N. Market St., Ste. 300
San Jose, CA 95113
t: 408.754.0121

Sacramento

111 Scripps Drive
Sacramento, CA 95825
t: 916.520.2777