


CORNER RECORD

Document Number 01-102

City of TRACY County of SAN JOAQUIN, California
Brief Legal Description 12th STREET AT HOLLY DRIVE



Government Corner Control
Meander Property
Rancho Other
Date of Survey 2-27-01

COORDINATES (Optional)


N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablished the corner:
FOUND 1 1/2" IRON PIPE NOT TAGGED ON 12th STREET APPROXIMATELY 15 FEET WEST OF
THE CENTERLINE OF HOLLY DRIVE.

A description of the physical condition of the monument as found and as set or reset: _____
FOUND 1 1/2" IRON PIPE WILL BE DESTROYED DUE TO PAVEMENT RECONSTRUCTION.
SET NAILS TAGGED LS6953 AS SHOWN ON SKETCH.

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on April 4, 2001.
Signed [Signature] L.S. 6953



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received APRIL 4, 2001 and examined and filed APRIL 9, 2001.

Signed [Signature] R.C.E. No. 28054
Title _____ County Surveyor



County Surveyors Comment _____

