


CORNER RECORD

Document Number 06-3
County of San Joaquin, California

City of Stockton
Brief Legal Description Section 11 of C.M. Weber Grant



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other

Date of Survey November 18, 2005

COORDINATES(Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NADV88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner.
Monument was established using swing ties from pre-construction corner record, CR-05-26.

A description of the physical condition of the monument as found and as set or reset: _____
Set 3/4" x 36" aluminum rod with 2 1/2" aluminum cap stamped RCE 32192 with a punch mark in monument well.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on January 11, 2006.
Signed [Signature] P.L.S. or R.C.E. No.: RCE 32192



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JANUARY 11, 2006 and examined and filed JANUARY 12, 2006.
Signed [Signature] P.L.S. or R.C.E. No.: 4440
Title Assistant County Surveyor
County Surveyor's Comment _____



(D.D. SHEET NO. 34)

FOUND CHISELED "+" IN
CORNER OF CONCRETE
FOOTING OF FENCE.

SET $\frac{3}{4}$ " X 36" ALUMINUM
ROD WITH 2 $\frac{1}{2}$ " ALUMINUM
CAP STAMPED RCE 32192
WITH A PUNCH MARK IN
MONUMENT WELL.

ODELL AVE.

46.79 FT.

58.22 FT.

62.46 FT.

ODELL AVE.

FOUND CHISELED "+" IN
THE TOP OF A CHAIN LINK
FENCE POST.

