


CORNER RECORD

Agency Index CR-17-133
Document Number _____

City of Tracy County of San Joaquin, California
Brief Legal Description Monument at intersection of MacArthur Drive and Arbor Avenue.



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other

Date of Survey March 24, 2017

COORDINATES (Optional)

N. _____ E. _____

Elevation _____

Units Metric U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

Complies with Public Resources Code §§8801-8819

Complies with Public Resources Code §§8890-8902

PLS Act Ref.: 8765(d) 8771 8773 Other:

Corner/Monument: Left as found Established Rebuilt Pre-Construction
 Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

Found 2" brass disk with punch stamped LS4479 inside monument well.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on March 28, 2017

Signed *[Signature]* P.L.S. or R.C.E. No. 8654
RICHARD J. HICKENBOTTOM



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received April 17, 2017

and examined and filed May 18, 2017

Signed *[Signature]* P.L.S. or R.C.E. No. 4842

Title County Surveyor

County Surveyor's Comment



LEGEND

- ⊗ SET NAIL W/ TAG "LS8654"
- SET IRON PIPE W/ PLUG "LS8654"
- ⊙ MONUMENT
- PP POWER POLE
- GLM GAS LINE MARKER
- TB TELEPHONE BOX
- EDGE OF PAVEMENT



Scale 1" = 30'

