CORNER RECORD Document Number <u>CR - 99-12</u> County of San Joaquin City of _____ Brief Legal Description TOWNSHIP CORNER - NORTHWEST CORNER SECTION 6. TOWNSHIP 4 SOUTH, RANGE 6 EAST, M.D.M. **CORNER TYPE COORDINATES** (Optional) T3S Control Government Corner R5E R6E NAD27 ☐ NAD83 ☐ Zone 36 31 Meander ☐ Property ☐ NAD83 Epoch_ 1 : 6 □ Other Rancho Elev. T4S Vert. Datum: NGVD29 □ NAVD88 □ Date of Survey May 4, 1999 Meas. Units: Metric □ Imperial Reestablished **V** Established □ Rebuilt Corner -Left as found □ Found and tagged Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Reestablished by using reference points and swing as per Corner Record No. 99-11. A description of the physical condition of the monument as found and as set or reset: Set 2 1/2" Brass Cap on a 3/4" X 36" Steel Rod in Monument Well with straddlers. Refer to the backside of this sheet for monument stamping. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with July 2: 19 99 the Land Surveyors' Act on Exp. 6-30-00 L.S. ______. Number ___4233 **COUNTY SURVEYOR'S STATEMENT** This Corner Record was received JULY 28 .1999 and examined and filed AUGUST m. Herato R.C.E. No. 21258 Title ____ County Surveyor's Comment

(D.D. Sheet Nos. 67, 68, 76)

