


CORNER RECORD

Document Number 00-239
County of San Joaquin, California

City of _____

Brief Legal Description ON FAIRCHILD 1320± W/O JACK TONE ROAD



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey JUNE 21, 2000

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner
REESTABLISHED LOCATION OF FOUND RR SPIKE PER SWINGS ON CR- 00-225
SEE SKETCH ON BACKSIDE

A description of the physical condition of the monument as found and as set or reset: _____
SET PK NAIL ON SURFACE. SEE SKETCH ON BACKSIDE

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors Act on Aug 3, 2000.

Signed _____ L.S. or R.C.E. Number 23341



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUGUST 4, 2000 and examined and filed AUGUST 8, 2000.

Signed Manuel Lopez R.C.E. No. 28054
Title _____ County Surveyor



County Surveyors Comment _____

(D.D. Sheet No. 26)



N.T.S.

