


CORNER RECORD

City of N/A

Document Number 02-18
County of San Joaquin, California

Brief Legal Description Record of Survey 21-168



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 4/9/99

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found 3/4" iron rod, no tag. I did not file this corner record in conformance with Board Rule 464 (c) regarding time of when the monument was found as I had no anticipation of it being destroyed.

A description of the physical condition of the monument as found and as set or reset: _____



SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on March 1, 2002.

Signed [Signature] L.S. ~~XXXXX~~ E. Number 7269

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MARCH 1, 2002 and examined and filed MARCH 5, 2002.

Signed [Signature] L.S. ~~XXXXX~~ E. No. 4440
Title ASSISTANT County Surveyor

County Surveyors Comment _____

SEC. 8

SEC. 9

50' R/W

JAHANT RD.

FD. S.J. CO. MON. BOLT
AT SEC. CORNER (R1) AND
WASHER, STAMPED L.S. 2239

SEC. 17
T.4N., R.7E.

SEC. 16

SCALE: N 1" = 300'

SECTION LINE

FD. PK NAIL
(NO RECORD)

S 74°25'53" W

1024.97' (M)

75°17'53" (M)

FD 3/4" I.R. (R3)
NO TAG, LEFT AS FOUND.

DUSTIN RD.

S 00°52'00" E 1608.58' (M)

S 00°52'00" E 748.49'

LEGEND

- FD FOUND
- I.R. IRON ROD
- R/W RIGHT-OF-WAY
- (M) MEASURED
- MONUMENT FOUND
- PM PARCEL MAP
- RS RECORD OF SURVEY

REFERENCES

- (R1) PM 6-26
- (R2) PM 18-107
- (R3) RS 21-168

40' R/W

FD S.J. CO. MON.
BRASS BOLT AND WASHER
AT 1/4 SEC. CORNER (R2)
STAMPED LS 2239