


CORNER RECORD

Document Number 05-26

City of Stockton

County of San Joaquin, California

Brief Legal Description Section 11 of C.M. Weber Grant



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other

Date of Survey June 17, 2005

COORDINATES(Optional)

N. _____

E. _____

Zone _____ NAD27 NAD83

NAD83 Epoch _____

Elev. _____

Vert. Datum: NGVD29 NADV88

Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found slightly bent nail at the approximate center line of Odell Ave. This monument is identified as the north-west terminus of the line labeled "N. 17°16'17" W. 430.00" on the Parcel Map filed in Book 20 of Parcel Maps, at Page 93, San Joaquin County Records.

A description of the physical condition of the monument as found and as set or reset: Found slightly bent nail.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on July 19, 2005.

Signed Michael R. Conrad R.C.E. No.: 32921



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUGUST 1, 2005 and examined

and filed AUGUST 2, 2005.

Signed Jeff Lund P.L.S. or R.C.E. No.: LS4440

Title Assistant County Surveyor

County Surveyor's Comment _____



(D.S. SHEET NO. 34)

SET CHISELED "+" IN
CORNER OF CONCRETE
FOOTING OF FENCE.

FOUND SLIGHTLY BENT
NAIL.


ODELL AVE.

46.79 FT.

58.22 FT.

62.46 FT.

ODELL AVE.



NOT TO SCALE

SET CHISELED "+" IN THE
TOP OF A CHAIN LINK
FENCE POST.