CORNER RECORD

Document Number 05-31 City of ____ Ripon County of San Joaquin D.N. 2003-028965 AND AS SHOWN ON 35 RS 144, S.J.C.R. **Brief Legal Description CORNER TYPE COORDINATES (Optional)** Ν **Government Corner** Control Ε Meander Property Zone Rancho NAD27 Other NAD83 NAD83 Epoch Elevation_ Date of Survey February 28, 2005 Vert. Datum: NGVD29 NADV88 Meas Units: Metric Imperial | Corner -Left as found X Found and tagged Established | Reestablished [X] Rebuilt | Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: SEE SKETCH A description of the physical condition of the monument as found and as set or reset: _ SEE SKETCH SURVEYOR'S STATEMENT LAND This Corner Record was prepared by me or under my direction in conformance with CRAIG C. BOWERS the Land Surveyors' Act on September 1 Exp. 12-31-06 No. 7049 COUNTY SURVEYOR'S STATEMENT This Corner Record was received <u>September</u> 20 <u>2005</u> and examined and filed OCTOBER No. 4440 Signed P.L.S. or R.C.E. Number 4440 Expires 9-30- O County Surveyor's Comment THIS CORNER RECORD IS NOT IN COMPLIANCE WITH BOARD RE SUBMITTAL WITHIN 90 DAYS FROM DATE OF SURVEY.

