| CORNER | RECORD | | Docum | nent Number | CR-13 | -264 | 9% | |
|--------------------------|--|--|------------------------|------------------------------------|-----------------|-----------------------|------------|--|
| City of (APN 053-120-04) | | | | County of San Joaquin , California | | | | |
| Brief Legal Descrip | tion Found EMBU |) monument in aqu | ueduct R | /W, near 1687 | 5 East Harne | ey Lane. | | |
| | | 14 | | | | | | |
| | co | | COORDINATES (Optional) | | | | | |
| | Government Corner | Control | | N | | | | |
| • 1 | Meander Rancho | ☐ Property ☐ Other | H | E. Zone | NAD | 027 NAD83 | | |
| 1 | | | | NAD83 Epoch | | | | |
| 516, T3N, R8E, MOM | Date of Survey Ma | arch 8, 2010 | | Elev. | | QUINOSOUNTE-2005-0 | | |
| | | | | Vert. Datum: | NGVD29 | NAVD88 | | |
| | | | | Meas. Units: | Metric | ☐ Imperial | X | |
| Corner - Left as for | ound 🔲 Found an | d tagged 🔲 Est | tablished | ☐ Rees | tablished 🛚 | Rebuilt | | |
| Identification and typ | e of corner found: Evid | ence used to identify | or proce | dure used to es | tablish or rees | tablish the corner: | | |
| An existing East Ba | ay Municipal Utility Di | istrict (EBMUD) bra | ass disc | monument, as | noted on Pa | ige 2, was found | on | |
| top of a concrete n | nanway structure mar | king the centerline | of the e | xisting aquedu | uct and contro | ol for the corrido | r | |
| R/W. | | | | | | | | |
| 91 | | | | | | | | |
| | | | | | | | | |
| A description of the | e physical condition o | of the monument as | s found a | and as set or re | eset: | | | |
| Āi | ent was referenced w | | | | | laced with a new | | |
| brass disc as desc | Nacional Control Contr | | | | | | | |
| | Hart San Control | | | | | | | |
| Reference EBMUE | Field Book 4411, Pa | age 20 (Poulsen/C | hou) | | | | | |
| | 1 | , | , | | | STAL LAND | * | |
| | | C CTATEMENT | | | | CONTE HIDOS | | |
| | SURVEYOR | SSIAICMEN | | | Mt. | (2) / (Fr/1) | 77.18 | |
| This Comes Boosed | SURVEYOR | | n oonform | ongo with | | STATE WASON | | |
| | was prepared by me or | under my direction in | | | PROPERTY | No. 4806 | TENOR . | |
| | | | n conform | | PROS | No. 4806 | A RESIDENT | |
| the Professional Lan | was prepared by me or | under my direction in | 20 | | - BROS | No. 4806 | TEION A | |
| | was prepared by me or | under my direction in | 20 | | | No. 4806 | EVOR 4 | |
| the Professional Lan | was prepared by me or d Surveyor's Act on | under my direction in | 20 . No | | | No. 4806 | EIOR A | |
| the Professional Lan | was prepared by me or d Surveyor's Act on | under my direction in July 3. P.L.S or R.C.E. | 20 . No | | | No. 4806 PROFESSION | EYOR & | |
| the Professional Lan | was prepared by me or d Surveyor's Act on | under my direction in July 3. P.L.S or R.C.E. | 20 . No | | | PROFESSIONA OMAS M | EVOR A | |

CP.L.Sor R.C.E. No. 26994 Signed

Title

County Surveyor's Comment:



