

CORNER RECORD

Document Number CR-13-349
County of SAN JOAQUIN, California

City of LATHROP

Brief Legal Description MONUMENT APPROXIMATELY 42'± SOUTHEAST OF THE INTERSECTION OF HARLAN ROAD AND D'ARCY PARKWAY. LOCATED IN SECTION 34, T.1S, R.6E, M.D.B.&M.

| | |
|-----------|-----------|
| NW 1/4 | NE 1/4 |
| SW 1/4 | SE 1/4 |

CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☐
Rancho ☐ Other ☒

COORDINATES (Optional)

N _____
E _____
Zone _____ NAD27 ☐ NAD83 ☐
NAD83 Epoch _____
Elev. _____
Vert. Datum: NVGD29 ☐ NVGD88 ☐
Meas. Units: Metric ☐ Imperial ☒

SEC. 34 T.1S, R.6E

Date of Survey 10-23-2013

Corner— Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND 5/8" REBAR WITH 1" CAP RCE 24029 IN MONUMENT WELL, AT APPROXIMATELY 42'± SOUTHEAST OF THE INTERSECTION OF HARLAN ROAD AND D'ARCY PARKWAY. LOCATED IN SECTION 34, T.1S, R.6E, M.D.B.&M.
FOUND MONUMENT AS SHOWN ON RECORD MAP FILED IN BOOK 31 OF MAPS AT PAGE 70,
SAN JOAQUIN COUNTY RECORDS.

A description of the physical condition of the monument as found and as set or reset:
MONUMENT IS IN AREA OF RECONSTRUCTION, SET TIES AS SHOWN ON PAGE 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyors' Act on NOVEMBER 12, 2013,

Signed [Signature] P.L.S. or R.C.E. Number 6953



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received November 20, 2013 and examined

and filed December 1, 2013

Signed Thomas M. Gau P.L.S. or R.C.E. No: 26994

Title County Surveyor

County Surveyor's Comment _____



LEGEND:

- ⊗ SET MONUMENT AS NOTED
- FOUND MONUMENT AS NOTED.
- S.J.C.R. DENOTES SAN JOAQUIN COUNTY RECORDS
- M.&P. DENOTES MAPS AND PLATS
- R.S. DENOTES RECORD OF SURVEYS
- (M) MEASURED DISTANCE. ALL DISTANCES ARE MEASURED UNLESS NOTED OTHERWISE.

REFERENCE:

- (R1) M.&P. 31-70, S.J.C.R.
- (R2) R.S. 34-108, S.J.C.R.

