


CORNER RECORD

Document Number CR-15-40
County of San Joaquin, California

City of _____

Brief Legal Description DURHAM FERRY ROAD (1.5 MILES WEST OF KASSON ROAD TO KASSON ROAD)
WITHIN RANCHO EL PESCADERO



CORNER TYPE

- Government Corner Control
- Meander Property
- Rancho Other

Date of Survey MARCH 23, 2015

COORDINATES (Optional)

N. SEE CHART ON BACKSIDE
 E. _____
 Zone 3 NAD27 NAD83
 NAD83 Epoch 2010.00
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Multiple monuments on the centerline and property line of Durham Ferry Road were found and surveyed. The
coordinates provided on this corner record are based on California HPGN D CA 10 HG (PID-AA4256), Epoch Date
2010.00.

A description of the physical condition of the monument as found and as set or reset: _____
SEE SKETCH ON BACKSIDE.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyors' Act on March 31, 2015.

Signed James E. Hart P.L.S. Number 8657

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received March 31, 2015 and examined
and filed April 10, 2015.

Signed Warren D. Smith P.L.S. No. 4842

Title Acting County Surveyor

County Surveyor's Comment _____



Point Name	Northing (Grid)	Easting (Grid)	Alignment
2	2066458.62	6330922.98	POT
3	2066440.72	6336237.38	Angle Point
4	2066465.71	6336227.19	Property Corner
5	2068173.73	6337991.03	IP
6	2067492.98	6337345.72	Control
7	2066430.80	6333275.82	Control
8	2066423.62	6334725.10	Control



N.T.S.

Notes:

No Attempt Was Made to Verify the Monument(s)

⊕ = Set 2"x2" Hub & Tack

● = Found Monument as Noted

N.T.S.=Not To Scale

To obtain ground distances, multiply grid inverses by a factor of 1.000067.

