


CORNER RECORD

Document Number CR-15-295
County of San Joaquin, California

City of _____

Brief Legal Description A.P.N. 063-040-23



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other

Date of Survey October 16, 2015

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Section 33, T3N, R.7E, MDB&M

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

See Sketch

A description of the physical condition of the monument as found and as set or reset: See Sketch

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on October 20, 2015

Signed [Signature] L.S. No. 7269



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received November 25, 2015 and examined and filed December 18, 2015.

Signed [Signature] L.S.-R.G.E. No. 4842

Title Acting County Surveyor



County Surveyor's Comment _____

SCALE:  1" = 60'

A.P.N. 063-040-24

S 89°30'00"E 290.50' (R1)(M)

80' R/W

N 01°23'00" W 225.00' (R1)(M)

A.P.N. 063-040-23

S 01°23'00" E 225.00' (R1)(M)

ALPINE ROAD

N 89°30'00"W 290.50' (R1)(M)

A.P.N. 063-040-25

LEGEND

- SET 3/4" IRON ROD
CAPPED "LS 7269"
- FOUND 3/4" REINFORCING ROD (R1)
NO TAG
- (M) MEASURED
- (R1) R.S. 25-135

15100