

CORNER RECORD

Agency Index CR-19-118


Document Number _____

City of Stockton County of San Joaquin, California

Brief Legal Description CORNER COMMON TO LOTS 6, 7, 16, AND 17, PER BOOK 25 OF MAPS AND PLATS, PAGE 108.

CORNER TYPE

COORDINATES (Optional)



- Government Corner
- Meander
- Rancho
- Control
- Property
- Other

Date of Survey July 19, 2019

N. _____ E. _____

Elevation _____

Units Metric U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

Complies with Public Resources Code §§8801-8819

Complies with Public Resources Code §§8890-8902

T.2N., R.6E., M.D.B.&M.

PLS Act Ref.: 8765(d) 8771 8773 Other:

Corner/Monument: Left as found Established Rebuilt Pre-Construction

Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

Found 1" iron rod, flush with existing ground, with plastic cap marked "LS 5342"(no record), located north of an existing electrolier and to the northwest of the existing parking lot, taken as marking the corner common to Lots 6, 7, 16, and 17, per map of Tract No. 1695, Hammertown Unit No. 4, filed in Book 25 of Maps and Plats, at Page 108, San Joaquin County Records.
Set new ties; see reverse for details.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on September 18, 2019.

Signed Scott J. Roberts (P.L.S.) or R.C.E. No. 9235



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received September 19, 2019

and examined and filed October 3, 2019.

Signed James E. Hart P.L.S. or R.C.E. No. 8657

Title County Surveyor

County Surveyor's Comment _____



LEGEND:

MONUMENT TIE LINE	-----
CURB	_____
MP	MAPS AND PLATS
LOT LINE	-----

REFERENCE:

(R1) 25-MP-108, SAN JOAQUIN COUNTY RECORDS

