Agency Index: CORNER RECORD Document Number: County of ______ SAN JOAQUIN _____, California City of LATHROP Brief Legal Description MONUMENT AT THE INTERSECTION OF LOUISE AVENUE AND HARLAN ROAD IN A MONUMENT WELL COORDINATES (Optional) CORNER TYPE Government Corner Control Elevation ☐ Property Meander U.S. Survey Foot Metric Units ○ Other Rancho Horizontal Datum Zone _____ Epoch Date ___ Date of Survey 06-16-2021 Vertical Datum T.1S, R.6E Complies with Public Resources Code SS8801-8819 Complies with Public Resources Code SS8890-8902 8773 Other: 8771 PLS Act Ref: 8765(d) Pre-Construction Established Rebuilt Left as found Corner/ ∇ Post-Construction Found and Tagged Referenced Monument: X Reestablished Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND THREE (3) CONCRETE NAILS WITH BRASS TAG STAMPED "L.S. 6953" AS SHOWN ON CORNER RECORD NO. 21-013, S.J.C.S.R. SET ONE (1) 2 1/2" BRASS DISK STAMPED "3-2021 L.S. 6953" IN MONUMENT WELL AT THE INTERSECTION OF HARLAN ROAD AND LOUISE AVENUE, ALL AS SHOWN ON PAGE 2. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with KENT A. HYSELL the Land Surveyors' Act on ______, ND, 6953 P.L.S. or R.C.E. Number 6953 COUNTY SURVEYOR'S STATEMENT This Corner Record was received October 14, 2021 and examined and filed November 4, 2021 P.L.S. OF R.C.E. No: 8657 County Surveyor's Comment _____

