CORNER RECORD

CR-22-233 Agency Index Document Number City of Lodi County of San Joaquin California Book 16, Page 12 of Parcel Maps, San Joaquin County Records Brief Legal Description **CORNER TYPE COORDINATES (Optional)** N. E. Government Corner Control Elevation Meander X U.S. Survey Foot Property Units Metric Rancho Other Horizontal Datum Zone Epoch Date Date of Survey June 27, 2022 Vertical Datum T3N R6E Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 PLS Act Ref.: × 8765(d) 8771 8773 Other: Left as found Established Rebuilt Pre-Construction Corner/ **Monument:** Found and tagged Reestablished Referenced X Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: ✓ See sheet #2 for description(s): Monument noted on diagram found during the course of construction. Established temporary ties, and after construction, returned and set 1.25" diameter brass disk stamped "Elson LS 7889" on concrete curb at original location. No boundary analysis was performed. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on June 28, 2022 Signed P.L.S. or R.C.E. No. 7889 **COUNTY SURVEYOR'S STATEMENT** This Corner Record was received and examined and filed Signed Title **County Surveyor's Comment**

BPELSG-2016

Page 1 of 2

NOTES: 135 27.5' 27.5 1. UNLESS OTHERWISE NOTED, MONUMENTS WERE OUTSIDE LIMITS OF CONSTRUCTION AND WERE NOT LOCATED AS A PART OF THIS SURVEY. 2. ORIGINAL MONUMENT DESTROYED DURING COURSE OF CONSTRUCTION. SET 1.25" DIAMETER BRASS DISK STAMPED "ELSON LS 7889" IN NEW CURB PER SET TIES. HUNTINGTON DRIVE LEGEND: PARCEL MAP, BOOK AND PAGE, SAN P.M. 27.5 JOAQUIN COUNTY RECORDS MAPS & PLATS, VOLUME AND PAGE, SAN M&P JOAQUIN COUNTY RECORDS P.U.E. PUBLIC UTILITY EASEMENT 27.5' 137 27.5 SEE NOTE 2. 41 Œ **(**) P.M. 16-12 135 335

NOT TO SCALE