
## **CORNER RECORD**

Document Number RIPON County of SAN JOAQUIN EAST 1/4 CORNER OF SEC. 30, T2S, R8E, M.D.B.M. Brief Legal Description **CORNER TYPE COORDINATES (Optional)** E. Government Corner Control Elevation **SEC** Meander Property Units U.S. Survey Foot Metric × Other Rancho Horizontal Datum 30 Zone **Epoch Date** Date of Survey July 14, 2021 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 PLS Act Ref.: 8765(d) **X** 8771 8773 Other: Left as found X Pre-Construction Established Rebuilt Corner/ **Monument:** Found and tagged Reestablished Referenced Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): **SURVEYOR'S STATEMENT** This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on August 12, 2022 Signed P.L.S. or R.C.E. No. **COUNTY SURVEYOR'S STATEMENT** January 4, 2023 This Corner Record was received Danuary 13, 2023.

P.L.S. OFR.C.E. No. 8657 and examined and filed Signed

**County Surveyor's Comment** 

Title



BPELSG-2016 Page 2 of 2