CR-23-235 CORNER RECORD Agency Index **Document Number** City of_ Lathrop County of San Joaquin , California Brief Legal Description Benchmark H1041 (HS0518) in SE 1/4, SE 1/4, Section 08, T02S R06E, MDM. **CORNER TYPE COORDINATES (Optional)** E. Government Corner Control Elevation Property Meander Units Metric X U.S. Survey Foot Other Rancho Horizontal Datum Zone_ _Epoch Date _ Date of Survey November 1, 2022 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 PLS Act Ref.: 8765(d) X 8771 8773 Other: Left as found Established Rebuilt Pre-Construction Corner/ Monument: Found and tagged Reestablished Referenced Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): Found H1041 (PID HS0518) benchmark (3 1/2" dia. brass disc) stamped "U.S. COAST & GEODETIC SURVEY" on the Northerly end of concrete abutment at the Northerly end of bridge 29-32L in Manthey Rd. and level with the road centerline. According to NGS guidance, level ties were made to three reference points for replacement upon upgrade construction. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on November 7, 2022 Signed LS8074 P.L.S. or R.C.E. No. **COUNTY SURVEYOR'S STATEMENT**

County Surveyor's Comment

This Corner Record was received

and examined and filed

Signed

LICENSE No. 8657

To Tracy

Д 4 α $\boldsymbol{\sqcap}$ 0

 \vdash