CR-23-240 **Agency Index** CORNER RECORD **Document Number** SAN JOAQUIN , California County of City of STOCKTON Brief Legal Description INTERSECTION OF HOLMAN ROAD AND HORSETAIL DRIVE **COORDINATES (Optional)** CORNER TYPE E. Elevation Government Corner Control U.S. Survey Foot ☐ Metric Units ☐ Property ☐ Meander Horizontal Datum ○ Other Rancho Zone Epoch Date Vertical Datum Date of Survey__5/2/2023 C.M. WEBER **GRANT** Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 Other: 8773 PLS Act Ref: **⊠** 8771 ☐ 8765(d) □ Pre-Construction ☐ Rebuilt ☐ Established Left as found Corner/ Monument: Post-Construction □ Referenced ☐ Found and tagged ☐ Reestablished Narrative of corner identified and monument as found, set, reset, replaced, or removed:

FOUND ONE 3/4" IRON PIPE IN MONUMENT WELL, NO TAG (R1); SET FOUR (4) CONCRETE NAILS WITH

CI	1	D	1		V	^	D	9	S	ГЛ	т	EN	ΛE	N	IT
3	U	K	V	ᆮ	Y	U	K	3	3	IA	, I			.IN	

This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on OCTOBER 4, 2023

Signed P.L.S. or R.C.E. No. 6953

BRASS TAG "LS 6953" AS WITNESS CORNERS, ALL AS SHOWN ON SHEET 2.

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received October 5, 2023


and examined and filed October 10, 2023

Signed Factor P.L.S. or R.C.E. No. 8657

Title County Surveyor

County Surveyor's Comment





See sheet #2 for description (s):

