CORNER RECORD

Document Number City of _____ County of _ San Joaquin California Parcels 1 and 2, P.M. 22-63 Brief Legal Description **CORNER TYPE** COORDINATES (Optional) E. Government Corner Control Elevation Property Units U.S. Survey Foot Meander Metric Rancho Horizontal Datum Epoch Date Zone Date of Survey June 1, 2024 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 8765(d) X 8771 PLS Act Ref.: 8773 Other: Left as found Established Rebuilt Pre-Construction Corner/ Monument: Found and tagged Reestablished Referenced Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on June 26, 2024 PLS 7889 P.L.S. or R.C.E. No. **COUNTY SURVEYOR'S STATEMENT** August 12, 2024 This Corner Record was received September 6, 2024.

Hart P.L.S. OFR.G.E. No. 8657 and examined and filed Signed **LICENSE** NO. 8657 Title **County Surveyor's Comment**

Agency Index

LEGEND:

- P.M. PARCEL MAP, BOOK AND PAGE, SAN JOAQUIN COUNTY RECORDS
- FOUND 3/4" IRON ROD WITH CAP, STAMPED "RCE 25835"
- FOUND 3/4" IRON ROD WITH CAP, STAMPED "RCE 25835" IN MONUMENT WELL

DESCRIPTION:

THIS CORNER RECORD IS FOR THE PURPOSE OF MONUMENT PRESERVATION. REFERENCES WERE SET FOR FOUND MONUMENTS AS NOTED ON DIAGRAM. NO BOUNDARY ANALYSIS WAS PERFORMED. THIS CORNER RECORD DOES NOT VERIFY THE MONUMENT(S) TO BE IN THE CORRECT POSITION.

