# **CORNER RECORD**

CR-25-199 Agency Index Document Number San Joaquin City of \_\_\_\_\_ County of \_ California Parcels 1 and 2, R.S. 40-77 Brief Legal Description **CORNER TYPE** COORDINATES (Optional) E. N. Government Corner Control Elevation X Property U.S. Survey Foot Meander Units Metric Rancho Other Horizontal Datum Zone Epoch Date Date of Survey May 6, 2025 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 **X** 8771 PLS Act Ref.: 8765(d) 8773 Other: Left as found Established Pre-Construction Rebuilt Corner/ Monument: Found and tagged Reestablished Referenced X Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s):

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on May 6, 2025

Signed

P.L.S. or R.C.E. No. PLS 7889



#### **COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received

ord was received May 30, 2025

Id filed June 5, 2025

P.L.S. OF R.C.E. No. 8657

and examined and filed

Signed

Title

**County Surveyor's Comment** 



BPELSG-2016 Page 1 of 2

## LEGEND:

- R.S. RECORD OF SURVEY, BOOK AND PAGE, SAN JOAQUIN COUNTY RECORDS
- FOUND MONUMENT AS NOTED PER CORNER RECORD 24-381, SAN JOAQUIN COUNTY SURVEYOR'S RECORDS
- FOUND MONUMENT IN MONUMENT WELL AS NOTED PER CORNER RECORD 24-381, SAN JOAQUIN COUNTY SURVEYOR'S RECORDS

## **DESCRIPTION:**

THIS CORNER RECORD IS FOR THE PURPOSE OF MONUMENT PRESERVATION. REFERENCES WERE SET FOR FOUND MONUMENTS AS NOTED ON DIAGRAM. NO BOUNDARY ANALYSIS WAS PERFORMED. THIS CORNER RECORD DOES NOT VERIFY THE MONUMENT(S) TO BE IN THE CORRECT POSITION.



S:\Projects\2024\24015\3.Drawings\24015\_CR dwg 05/07/25 1:36pm-CARTER-XREFS: 24015\_HC.dwg

LIMITS OF CONSTRUCTION AREA

